



\* Please note that after fitting the Flash Lube system to the engine, the vacuum connection was made in between the second and third cylinder. Therefore, the lubricant was only distributed into cylinder no. 2 and 3, which can be seen from the valve wear pattern of these cylinders compared to n. 1 and 4. This may be a very clear result to convince your customers that the system works.