

IDENTIFICATION OF THE VEHICLE.

BRAND / TYPE VEHICLE :
ENGINE TYPE :
KILOMETERS BEFORE FITTING :

CITROËN XANTIA 1.8i-8V
LFZ
42951

		Measured valve clearance <i>before using Flash Lube</i> (1/10 mm):							
		Cylinder 1		Cylinder2		Cylinder 3		Cylinder 4	
	Date	in/in	out/out	in/in	out/out	in/in	out/out	in/in	out/out
Check nº.1	10-12-99	20/20	40/40	20/20	40/40	20/20	40/40	20/20	40/40
Check nº.2	22-03-00	10/15	10/05	10/10	10/10	10/10	05/05	15/10	05/10
Valve wear (56432km)		10/05	30/35	10/10	30/30	10/10	35/35	05/10	35/30
Check nº.3	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/
Check nº.4	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/
Check nº.5	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/
Check nº.6	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/
Check nº.7	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/

		Measured valve clearance <i>after using Flash Lube</i> (1/10 mm):							
		Cylinder 1		Cylinder2		Cylinder 3		Cylinder 4	
	Date	in/in	out/out	in/in	out/out	in/in	out/out	in/in	out/out
Check nº.1	22-03-00	20/20	40/40	20/20	40/40	20/20	40/40	20/20	40/40
Check nº.2	24-05-00	20/20	35/35	20/20	35/35	20/20	35/35	20/20	35/35
Valve wear (71456km)		0/0	05/05	0/0	05/05	0/0	05/05	0/0	05/05
Check nº.3	01-07-00	20/20	35/35	20/20	35/35	20/20	35/35	20/20	35/35
Valve wear (86342km)		0/0	05/05	0/0	05/05	0/0	05/05	0/0	05/05
Check nº.4	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/
Check nº.5	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/
Check nº.6	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/
Check nº.7	- -	/	/	/	/	/	/	/	/
Valve wear		/	/	/	/	/	/	/	/

